



WIRING DIAGRAM



SHADED PORTION OF BAR CHART INDICATES THE PROPORTIONAL TIMES THAT INTERNAL TIMER CONTACTS ARE CLOSED.

WIRING DIAGRAM
P/N 131907400